



STADLER®
MOTORRADBEKLEIDUNG

CARE INSTRUCTIONS

textile motorcycle clothing

**The durability and functionality of any garment also depends on proper care.
So please always note the sewn-in care label.**

Regular washing does not harm the GORE-TEX membrane. Rather it ensures a high life expectancy and constant functionality of the garment.

Before washing motorcycle clothing, always remove the protectors first, close Velcro and zippers and snaps!



WASHING

Please make sure that you pay attention to the sewn-in care label!

If not stated otherwise, wash the garment in the washing machine with a detergent which is suitable for membrane clothing, in a delicate machine cycle (without spinning) at up to 30°C. Pre-treat heavy soiling and stains with a commercial stain remover.

In order to avoid detergent residues on the GORE-TEX material, please rinse sufficiently (Repeat the rinsing process).

Do not use fabric softener!!!



IRONING

By ironing (without steam) according to the care label or in the dryer at low temperature you can reactivate the water-repellent impregnating effect.



LAUNDRY DRYER

Dry at low drum filling and at low temperature.



BLEACHING

Do not use any chlorine bleach.



DRY-CLEANING

If it is not specified otherwise on the care-label, cleaning is possible. However washing in the washing machine is preferred.

Advice: Maintenance is better when done often and with less detergent than seldom with a lot of detergent.

We suggest:



IMPREGNATION

Impregnation in no way impairs the function of the GORE-TEX membrane. Quite the contrary, well-impregnated clothing repels dirt and water. A soaked outer fabric causes heat loss. So a good impregnation therefore protects against cold as well. The shell fabric of the garments with GORE-TEX product technology are already impregnated at the time of manufacture.

Our motorcycle clothing is equipped with a factory impregnation that allows water to bead off and thus prevents the outer shell from becoming soaked immediately. However, this water and dirt repellent layer does not last permanently. Even superficial contamination and dirt, but also proper washing of the clothing reduces the effect of the impregnation. However, this can be reactivated and restored and is therefore not a reason for complaint.

The beading effect can be reactivated by a short heat treatment at low temperature in the dryer or by ironing (without steam/with cloth between garment and ironing sole) according to the care label.

Depending on the usage, but at the latest when water no longer beads off as usual, the clothing should be treated with a waterproofing agent suitable for breathable clothing.

REPAIR

In spite of all caution, the clothing can become damaged. Even small tears and holes cause water to get inside, in the case of water-proof clothing. Due to the special construction of the GORE-TEX clothing, such damages should be repaired only by a specialist. In this case, please contact your retailer or our sales team.

Attention:

Only washed garments will be repaired!